

Smithco Crew #1 Juan V
Site cleanup, hydrotesting, and misc appurtenances on NM502

Spear D Crew #1
FWD20_POJ from White Sands Tank
Pipeline installation

Turtle Tank Site
Gallery (tentative): steel and drywall painting inside Chlorination Building
Donner: installing plumbing and HVAC inside Chlorination Building

Pojoaque Booster Pump Station
Gallery (backup location): steel painting inside building
Donner (backup location): installing plumbing and HVAC inside building

Spear D Crew #2
Manhole installation on installed pipelines
FWD60/69/55/61/68_POJ

